

EPA Official Record

Notes ID: 957E4DA9760BA8A5678A93B8B339551F

From: Chris Hill <chris.hill@chk.com>

To: "Florentino, Gene" <GFlorentino@ene.com>

Copy To: "Lukert, George" <GLukert@ene.com>; Robert Puls/ADA/USEPA/US@EPA; Susan Mravik/ADA/USEPA/US@EPA

Delivered Date: 09/15/2011 02:59 PM EDT

Subject: RE: Drilling Quotes

ATTACHMENT: Sec 33-14-15 H-1 cert SUP 9-8-11.pdf
[IMAGE]

Gene,

I will hold off on contacting any water well drillers for quotes.

I have attached the proposed surface location plat for your reference. There is not much, if any, flexibility in the pad location.

Please let me know if you have any additional questions.

Thanks,

Chris

From: Florentino, Gene [mailto:GFlorentino@ene.com]

Sent: Thursday, September 15, 2011 12:47 PM

To: Chris Hill

Cc: Lukert, George; Puls.Robert@epamail.epa.gov; Mravik.Susan@epamail.epa.gov

Subject: Drilling Quotes

Chris,

We talked to Bob today. It still may be a bit premature to obtain quotes at this time until we resolve well placement issues (hopefully next Monday). Following that meeting, we hope to have a scope that can be drafted for drilling.

Do you have a plat of the proposed well pad/production well and owners/boundaries? We really need an updated site plan to make well placement

decisions. How flexible is the pad location (i.e., can it be moved to the west/north west to minimize interference with RR property with regard to MW placement?

Gene

From: Chris Hill [mailto:chris.hill@chk.com]
Sent: Thursday, September 15, 2011 12:51 AM
To: Florentino, Gene
Cc: Lukert, George
Subject: RE: Rotary Capabilities

[IMAGE]

Gene,

Would you like me to begin rounding up some quotes? I spoke with Bob this afternoon, he said you might be already on top of this...? If not, I am more than happy to get the ball rolling.

Thanks,

Chris

From: Florentino, Gene [mailto:GFlorentino@ene.com]
Sent: Wednesday, September 14, 2011 7:20 AM
To: Chris Hill
Cc: Puls.Robert@epamail.epa.gov; Lukert, George
Subject: FW: Rotary Capabilities

Chris,

As I mentioned yesterday, attached and below is info about Major Drilling. We have worked with them in the past.

Gene

From: Larson, Don J [mailto:Don.Larson@majordrilling.com]
Sent: Tuesday, September 13, 2011 6:21 PM
To: Florentino, Gene
Subject: Rotary Capabilities

Hi Gene,

Thanks for the inquiry and conversation today regarding Major's rotary capabilities. We run a fleet of rotary rigs including Schramm T130s and one Schramm 450 which would be capable of well installations to depths of +5,000 feet I have included our company SOQ for your review.

Please keep us in mind for any upcoming opportunities.

Best Regards,

Don Larson

Sales and Business Development Manager - Environmental

503-925-1133 (office)

503-347-8119 (cell)

Don.larson@majordrilling.com

www.majordrilling.com

Major Drilling Environmental, LLC is a full service drilling company, offering Sonic,

Hollow Stem Auger, Limited Access, Mud Rotary, Coring, Direct Push, and Well

Development Services. Our Portland Oregon office is located at 13565 SW Tualatin

Sherwood Rd, Suite 700 in Sherwood, Oregon. We also have offices in Seattle-Washington,

Salt Lake City - Utah, Huntsville - Alabama, and Little Falls - Minnesota. Quotes and scheduling

for our Portland office can be directed to Terry Jacques at (503) 925-1133.

Well Driller #10432

Oregon CCB #191664

Washington Driller #MAJORDE902MG

This email communication is intended only for the person or entity to which it is addressed and may contain confidential and/or privileged information. Any use of this information by persons or entities other than the intended recipient is prohibited. If you received this in error, please contact the sender and delete the email and all copies (electronic or otherwise) immediately.

[Click here to report this email as spam.](#)

This email (and attachments if any) is intended only for the use of the individual or entity to which it is addressed, and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this email is not the intended recipient, or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately by return email and destroy all copies of the email (and attachments if any).

This email (and attachments if any) is intended only for the use of the individual or entity to which it is addressed, and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this email is not the intended recipient, or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately by return email and destroy all copies of the email (and attachments if any).

***** ATTACHMENT NOT DELIVERED *****

This Email message contained an attachment named image001.jpg which may be a computer program. This attached computer program could contain a computer virus which could cause harm to EPA's computers, network, and data. The attachment has been deleted.

This was done to limit the distribution of computer viruses introduced into the EPA network. EPA is deleting all computer program attachments

sent from the Internet into the agency via Email.

If the message sender is known and the attachment was legitimate, you should contact the sender and request that they rename the file name extension and resend the Email with the renamed attachment. After receiving the revised Email, containing the renamed attachment, you can rename the file extension to its correct name.

For further information, please contact the EPA Call Center at (866) 411-4EPA (4372). The TDD number is (866) 489-4900.

***** ATTACHMENT NOT DELIVERED *****

- Sec 33-14-15 H-1 cert SUP 9-8-11.pdf